


# SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service  
Washington, DC



U.S. Department  
of Transportation

**Federal Aviation  
Administration**

No. CE-04-31  
December 9, 2003

*[www.faa.gov](http://www.faa.gov) - Search "SAIBs"*

*This is information only. Recommendations aren't mandatory.*

---

## Introduction

This Special Airworthiness Information Bulletin informs owners and operators of **Britten Norman BN2, BN2B, BN2T (Islander) series aircraft**, that B-N Group Ltd. has issued a *mandatory* service bulletin (SB) 292, issue 1 to insure the correct installation of retainer on elevator trim tab lever bolt.

## Background

During routine maintenance, mechanics discovered the incorrect installation of the elevator trim tab connecting bolt retainer hardware. This condition may permit the elevator trim tab connecting bolt to disconnect from the control rod and elevator trim tab lever.

## Recommendation

We aren't issuing an AD at this time, but highly recommend that you comply with the manufacturer's SB 292, issue 1.

## For Further Information Contact

Taylor Martin, Aerospace Engineer, FAA Small Airplane Directorate, ACE 112, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4138; fax: (816) 329-4090; email: [taylor.martin@faa.gov](mailto:taylor.martin@faa.gov)

For copies of the SB, contact B-N Group Limited. Bembridge, Isle of Wight, United Kingdom PO35; phone: +44 (0) 870 881 5064; fax: +44 (0) 870 881 5065